
KB3000-AHL

Adjustable Height Changing Station







Warning! Risk of injury by crushing. Ensure the area underneath the stretcher is kept clear of obstructions before operating. Keep clear of the area above the stretcher when stowing.



Caution! Keep clear of moving parts when operating. Ensure there are no obstructions when moving the guard into position.



Action! Always deploy the guard before moving the changing table with a person on the stretcher.

This KB3000-AHL will require maintenance to ensure it is safe to operate. This service must be carried out by an approved, trained professional.